



Worldwide repairs carried out with PolymerMetal[®]

REP-# 008



A leakage on a transformer (240.000 kVA) was repaired with MM-metal oL-steelceramic and Hardener red without cutting of the station. After this a second layer with MM-metal oL-steelceramic and Hardener yellow was applied.

MultiMetall
the MetalExistenceCompany[®]