



Worldwide repairs carried out with PolymerMetal®

REP-# 099



A leakage in a 154 KV P.O.F. insulation pipe was sealed using MM-metal oL-steelceramic and Hardener red working with the direct-MM-bonding method. In addition corrosion damages of the piping were removed by applying MM-metal SS-steel, liquid and Hardener yellow, liquid. Oil pressure 200 psi, diameter of the piping 300 mm, oil quality polybdenum.

MultiMetal
the MetalExistenceCompany®