



*Worldwide repairs carried out with PolymerMetal®*

**REP-# 005**



Repair of a marine engine with MM-metal SS-steelceramic and Hardener yellow. Damage: cracked packing surface between cooling water space and cylinder liner.

**MultiMetall**  
the MetalExistenceCompany®