



Worldwide repairs carried out with PolymerMetal[®]

REP-# 051



Repair of a water piping which was under pressure by using MM-metal UW and Hardener UW3. The sealing has been carried out while water was still escaping.

MultiMetall
the MetalExistenceCompany[®]