



Worldwide repairs carried out with PolymerMetal[®]

REP-# 082



Casting defects on compressor housings were repaired using MM-metal S-steel.

MultiMetall
the MetalExistenceCompany[®]