



Worldwide repairs carried out with PolymerMetal®

REP-#151



Into an old cracked valve with a broken flange, a pipe with a suitable diameter was inserted and fixed by using the PolymerMetal MM-metal SS-steel. Then this connection was secured by several screws.

MultiMetal
the MetalExistenceCompany®